

U 4/092

NATCA 60-143

Chief, EUCA  
Chief, KUCLUB

Chief, NATCA

3 February 1960

Operational/Engineering  
RR-33 Receiver

EUCA 59-2216, 17 November 1959

(RAD/LAB)

1. Returned herewith is the RR-33 receiver and instructions which were forwarded with reference. We regret the delay in returning the unit, but it was inoperative upon receipt and had to be sent to our base station for inspection. There it was found that one of the transistors had come out of its socket. The small plastic case containing the headset was also found broken when the unit was received at NATCA.

2. The receiver works well, but its limited frequency range and lack of a BFO, particularly the latter, limit its usefulness in this area.

3. Many thanks for forwarding the receiver as we were anxious to see it and, again, our apologies for the delay in returning it to you.

50X1  
50X1

50X1

## Attachments:

- 1 - RR-33 Receiver
- 2 - RR-33 Instructions

## Distribution:

EUCA: 2 w/attachments  
KUCLUB: 3 w/o attachments

DOCUMENT NO. \_\_\_\_\_  
NO CHANGE IN CLASS. ☐  
☐ DECLASSIFIED  
CLASS. CHANGED TO: TS S 2010  
NEXT REVIEW DATE: \_\_\_\_\_  
AUTH: HR 70-2  
DATE: 9 DEC 1980 REVIEWER: 064540

INFORMATION COPY ONLY

~~SECRET~~